


TROUBLESHOOTING	
Ignition Coil Test Gap / Primary Ω / Secondary Ω	6mm / 2.75 Ω \pm 10% / 7.9K Ω \pm 20%
Pulse Coil or Pick-up Coil Color Code / Ω	Org ~ Bik / Yellow ~ Bik / Gry ~ Bik / 560 Ω \pm 20%



- | | | | |
|----|-----------------|------------------------------------|---|
| 1 | 2F3-81671-10-00 | COIL, pick up | 1 |
| 2 | 97801-06014-00 | SCREW, pan head | 3 |
| 3 | 92903-06200-00 | WASHER, plain (92901-06200) | 3 |
| 4 | 2F3-81653-11-00 | GOVERNOR ASS'Y | 1 |
| 5 | 93604-08071-00 | PIN, dowel (4-8) | 1 |
| 6 | 2F3-81655-00-00 | WASHER | 1 |
| 7 | 90105-C8067-00 | BOLT | 1 |
| 8 | 1J7-81632-00-00 | PLATE, timing | 1 |
| 9 | 98503-05012-00 | SCREW, cylinder head (98301-05012) | 1 |
| 10 | 92903-05100-00 | WASHER, spring (92901-05100) | 1 |

