



| Ref. No. | Part Number     | Description                                | Qty. |
|----------|-----------------|--|------|
| 1        | 90465-10113-00  | CLAMP .....                                | 1    |
| 2        | 90465-08112-00  | CLAMP .....                                | 2    |
| 3        | 90465-08139-00  | CLAMP .....                                | 1    |
| 4        | 97301-06010-00  | BOLT .....                                 | 3    |
| 5        | 2F3-81671-10-00 | COIL, pick up.....                         | 1    |
| 6        | 2F3-81653-11-00 | GOVERNOR ASS'Y.....                        | 1    |
| 7        | 3H5-81675-01-00 | WASHER, special(3H5-81675-00)              | 3    |
| 8        | 3J3-81674-00-00 | BOLT .....                                 | 3    |
| 9        | 93604-08071-00  | PIN, dowel .....                           | 1    |
| 10       | 3J3-81652-00-00 | BOLT .....                                 | 1    |
| 11       | 2F3-81655-00-00 | WASHER .....                               | 1    |
| 12       | 90465-08116-00  | CLAMP .....                                | 2    |
| 13       | 1T4-81624-00-00 | CLAMP .....                                | 1    |
| 14       | 90465-10137-00  | CLAMP .....                                | 1    |
| 15       | 1J7-81632-00-00 | PLATE, timing .....                        | 1    |
| 16       | 98503-05012-00  | SCREW, cylinder head<br>(98301-05012)..... | 1    |
| 17       | 92903-05100-00  | WASHER, spring (92901-05100)               | 1    |
| 18       | 90465-08017-00  | CLAMP .....                                | 1    |

| TROUBLESHOOTING   |   |  |
|---|---|--|
| Ignition Coil Test Gap/Primary $\Omega$ /Secondary $\Omega$ | 6mm / 2.75 $\Omega$ $\pm$ 10% / 7.9K $\Omega$ $\pm$ 20% |  |
| Pulser Coil or Pick-up Coil Color Code / $\Omega$           | Org ~ Blk / Yel ~ Blk / Gry ~ Blk / 700 $\Omega$        |  |